

ACTIVITIES REPORT
SUPERFUND EMERGENCY MANAGEMENT BRANCH (6SF-E)
February 14, 2017

CWA 311 SPILL PREVENTION CONTROL AND COUNTERMEASURE (SPCC) AND FACILITY RESPONSE PLAN (FRP) INSPECTIONS: SEE ATTACHED TABLE

CATAHOULA OIL SPILL, LARTO, LA: The EPA continues to coordinate oil well Plugging/Abandonment (P&A) plans with the Army Corps of Engineers as well as with State officials. Subcontract approval for the P&A work has been provided. The EPA and EPA contractors plan to mobilize to the site to begin P&A work on Tuesday, February 21. (Crossland, x2721)

CORPUS CHRISTI DRINKING WATER RESPONSE FINAL DATA POSTING: Final lab data from the EPA Houston Lab has been received and assimilated into data tables and maps. Data tables and maps will be shared with TCEQ via External Affairs. The data is expected to be posted on the TCEQ website. (Crossland, x2721)

CORPUS CHRISTI DRINKING WATER RESPONSE – VALERO VISIT TO REGIONAL OFFICE: The week of March 6th, Valero has requested a meeting with Superfund staff to discuss the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) 104e Information Request that was issued after the Corpus Christi incident occurred. Water Quality and Enforcement Divisions will also be invited. Valero has indicated that they intend to share the details that led up to the incident. (Crossland, x2721)

AMARILLO PHOSPHINE INCIDENT, AMARILLO, TX: EPA has received the final results for the confirmative air sampling that was completed within the house. The data is being validated and upon validation completion will be shared with Unified Command. The preliminary data for the air sampling was shared with Unified Command in early February. (Crossland, x2721)

METAIRIE ENERGY OIL SPILL, PLAQUEMINE, LA: The majority of free oil and oiled debris has been collected and is staged on-site awaiting disposal. Disturbance of the underwater sediment within the impacted area generates additional oil at the surface of the water. A significant amount of oil may be resting on the surface of the sediment. Sediment sampling has begun and will continue through the week. Sampling results will determine the strategy to address any submerged oil. EPA, US Coast Guard (USCG), Louisiana Oil Spill Coordinator's Office (LOSCO), and Louisiana Department of Environmental Quality (LDEQ) are performing oversight of the clean-up efforts. (Crossland, x2721)

CLEAN AIR ACT RISK MANAGEMENT PLAN (RMP) INSPECTIONS:

Note: Facilities are classified as "high risk" based on one or more of the following factors: the proximity of a significant population within the worst case release scenario radius, a hazard index greater than 25, or the occurrence of a significant accident at the facility involving an RMP chemical.

- **SIMMONS VAN BUREN, AR:** The EPA Region 6 Risk Management Plan staff will be conducting an inspection of the Simmons Cook facility in Van Buren, Arkansas on February 15, 2017. The regulated facility is a High Risk facility under the National Enforcement Initiative for ammonia. Appropriate enforcement actions will be taken based on the final inspection report submitted to the Enforcement Officer. **(Crossland, x2721)**
- **PILGRIMS PRIDE, MOUNT PLEASANT, TX:** The EPA Region 6 Risk Management Plan staff will be conducting an inspection of the Pilgrims Pride facility in Mount Pleasant, Texas on February 22, 2017. The regulated facility is a High Risk facility which falls under the National Enforcement Initiative for ammonia. Appropriate enforcement actions will be taken based on the final inspection report submitted to the Enforcement Officer. **(Crossland, x2721)**
- **INEOS USA LLC/HOBBS FRACTIONATION COMPLEX, SEMINOLE, TX:** The EPA Region 6 Risk Management Plan staff will be conducting an inspection of the INEOS USA LLC/Hobbs Fractionation Complex, Seminole, Texas on March 1, 2017. The regulated facility is a High Risk facility which falls under the National Enforcement Initiative for gas processing. Appropriate enforcement actions will be taken based on the final inspection report submitted to the Enforcement Officer. **(Crossland, x2721)**
- **EQUISTAR MARINE, CORPUS CHRISTI, TX:** The EPA Region 6 Risk Management Plan staff will be conducting an inspection of the Equistar Marine facility, in Corpus Christi, Texas on March 7, 2017. The regulated facility is a High Risk facility which falls under the National Enforcement Initiative for gas processing. Appropriate enforcement actions will be taken based on the final inspection report submitted to the Enforcement Officer. **(Crossland, x2721)**
- **MARK WEST, CORPUS CHRISTI, TX:** The EPA Region 6 Risk Management Plan staff will be conducting an inspection of the Mark West facility in Corpus Christi, Texas on March 8, 2017. The regulated facility is a High Risk facility which falls under the National Enforcement Initiative for gas processing. Appropriate enforcement actions will be taken based on the final inspection report submitted to the Enforcement Officer. **(Crossland, x2721)**

MEXUS EXERCISE, HOUMA, LA: On March 6 EPA Region 6 will participate in the Keathley Canyon Preparedness for Response Exercise Program (PREP) 2017 Full-Scale Exercise. This joint U.S. and Mexican government exercise aims to improve effectiveness of the Southeast Louisiana Area Contingency Plan, the Anadarko Petroleum Corporation Oil Spill Response Plan, and the MEXUSGULF Regional Annex of the Joint Contingency Plan between the Mexican Navy and USCG. Federal, state and local governments will participate. Scenario involves a worst case discharge of 206,000 barrels of oil per day (bopd). Oil originates in US EEZ (Economic Exclusion Zone) and migrates into MX EEZ and Texas waters. EPA R6 will participate at the Incident Command Post by providing direction related to the approval process for use of dispersants (surface and subsea) and other available technology. **(Crossland, x2721)**

CHOCTAW BAYOU OIL SPILL, IBERVILLE PARISH, LA: The Responsible Party's (RP) contractor, Oil Mop (OMI) continues to collect free oil and oily debris from the impacted areas. The oil is very difficult to collect because soap was applied to the oil for many months. OMI began sediment sampling on February 12. Sample results for the storage tanks should also be received this week and will be used to determine disposal options. EPA continues to provide oversight and coordinate with Louisiana Oil Spill Coordinator's Office (LOSCO), Louisiana Department of Environmental Quality (LDEQ) and the RP. At this time the RP continues to be financially responsible for the cleanup activities. **(Crossland, x2721)**

EXPLO SYSTEMS, CAMP MINDEN, LA: The total amount of M6 destroyed to date is 13,039,997 pounds, equating to 81.5%. The Citizen's Advisory Group (CAG) meeting was held on February 13th and the Contained Burn System was the main topic of discussion. The site On-Scene Coordinator (OSC) and Community Involvement Coordinator (CIC) met with the Chairman of the Webster Parish Police Jury. The Chairman's main concerns regarded the prior National Priority List (NPL) listing of the site and other waste potentially buried at Camp Minden that was not covered by this current removal or past EPA assessments. The Louisiana Military Department (LMD) revised the L2 Clean-up work plan and submitted a final revision to EPA and Louisiana Department of Environmental Quality (LDEQ). EPA plans to conditionally approve the work plan subject to LMD posting the document to the LMD website for public feedback. EPA reviewed LMD's submittal of the Operations and Maintenance Plan and provided comments. The next CAG Meeting is scheduled for March 13, 2016. **(Crossland, x2721)**

Facility Name	Statute	Action	City or County	State	Projected Inspection Date	Targeted Prompt
Anderson TB, Hough Oil & Gas	CWA	Inspection	Osage County	OK	2/15/2017	Referral/Complaint
Bluestem D&E TB, SM Oil & Gas, Inc.	CWA	Inspection	Osage County	OK	2/15/2017	Referral/Complaint
Sol Robinson/Thomas TB, Graham Oil	CWA	Inspection	Osage County	OK	2/16/2017	Referral/Complaint
B.M. Johnson Lease TB, Jireh Resources	CWA	Inspection	Osage County	OK	2/16/2017	Referral/Complaint
B.J. Lease TB, G.C. Bickham	CWA	Inspection	Pontotoc County	OK	2/22/2017	Referral/Complaint
Hoffman No. 1 TB, Randy & Jan Walker	CWA	Inspection	Seminole County	OK	2/22/2017	Referral/Complaint
RB No.2 TB, Phoenix Oil & Gas	CWA	Inspection	Pottawatomie County	OK	2/22/2017	Referral/Complaint

West Lake Verret Facility, White Oak	CWA/OPA	Inspection	Morgan City	LA	2/22/2017	USCG Referral (SPCC/FRP/Drill)
LM #36-1, ALM #37-1 Commingling Facility, Castex	CWA/OPA	Inspection	Houma	LA	2/23/2017	FRP Approval
Fina Fee D #1, Bayou Jean LaCroix Field, Desco	CWA/OPA	Inspection	Houma	LA	2/23/2017	FRP Approval
Anderson Lease TB, Citation Oil & Gas	CWA	Inspection	Stephens County	OK	3/6/2017	Referral/Complaint
WF George TB, Urban Oil & gas	CWA	Inspection	Wichita County	TX	3/6/2017	Referral/Complaint
Pumpco Pipeline Facility, Pumpco, Inc	CWA	Inspection	Wise County	TX	3/7/2017	Referral/Complaint
Clovelly Central Facility, TPIC	CWA/OPA	Inspection	Gaillano	LA	3/7/2017	FRP Approval
Lake Raccourci, Forza	CWA/OPA	Inspection	Leeville	LA	3/7/2017	FRP Approval
Grand Lake Storage and Transfer Facility, Shoreline	CWA/OPA	Inspection	Cameron Parish	LA	3/21/2017	FRP Approval
Mallard Bay CF #1, TCOE Energy	CWA/OPA	Inspection	Cameron Parish	LA	3/21/2017	FRP Approval
193 Dock Facility, Martin	CWA/OPA	Inspection	Cameron Parish	LA	3/21/2017	FRP Approval
Mermentau Treatment Facility, R360	CWA/OPA	Inspection	Mermentau	LA	3/23/2016	FRP Approval
Mermentau Facility, Crosstex	CWA/OPA	Inspection	Mermentau	LA	3/23/2017	FRP Approval
Jennings Barge Terminal, Canal Refining	CWA/OPA	Inspection	Mermentau	LA	3/23/2017	FRP Approval
Port Terminal, Southcoast Terminals	CWA/OPA	Inspection	Houston	TX	4/4/2017	FRP Approval
Houston Refinery, Valero	CWA/OPA	Inspection	Houston	TX	4/4/2017	FRP Approval
Houston Terminal, Westway Terminals	CWA/OPA	Inspection	Houston	TX	4/6/2017	FRP Approval
Pasadena Terminal, Motiva	CWA/OPA	Inspection	Houston	TX	4/6/2017	FRP Approval
DPC Industries, Inc.	CAA/RMP	Inspection	Corpus Christi	TX	2/1/2017	EJ/MVD Community
Tanner Industries	CAA/RMP	Inspection	Natalbany	LA	2/7/2017	High Risk, NEI
Carrollton Water Purification Plant	CAA/RMP	Inspection	New Orleans	LA	2/8/2017	High Risk
Hackberry Storage	CAA/RMP	Inspection	Hackberry	LA	2/14/2017	High Risk

Jacobs A. Hands WWTP	CAA/RMP	Inspection	Las Cruces	NM	2/14/2017	
Pilgrim's Pride – Mt. Pleasant Prep	CAA/RMP	Inspection	Mt. Pleasant	TX	2/15/2017	High Risk, NEI
INEOS USA LLC/Hobbs Fractionation Complex	CAA/RMP	Inspection	Seminole	TX	2/21/2017	High Risk
MarkWest Javelina	CAA/RMP	Inspection	Corpus Christi	LA	2/22/2017	High Risk, EJ/MVD
Dalhart Consumers Fuel Coop	CAA/RMP	Inspection	Texline	TX	3/2/2017	
Simmons Foods, VB Main	CAA/RMP	Inspection	Van Buren	AR	3/8/2017	
Simmons Foods, VB Cook & DC	CAA/RMP	Inspection	Van Buren	AR	3/7/2017	High Risk
DPC Industries, Inc.	CAA/RMP	Inspection	Albuquerque	NM	3/14/2017	High Risk
Air Products Catoosa ESM	CAA/RMP	Inspection	Catoosa	OK	3/21/2017	High Risk
Brenntag SW, Inc. Port of Catoosa	CAA/RMP	Inspection	Catoosa	OK	3/22/2017	High Risk
American Cold Storage	CAA/RMP	Inspection	Tulsa	OK	4/4/2017	NEI
Trimac Tulsa Transloading	CAA/RMP	Inspection	Tulsa	OK	4/5/2017	
City of Pampa WTP	CAA/RMP	Inspection	Pampa	TX	4/11/2017	
Battle Ridge Processing Plant	CAA/RMP	Inspection	Edmond	OK	4/18/2017	High Risk
OSU Water Treatment Plant	CAA/RMP	Inspection	Stillwater	OK	4/19/2017	
George's Further Processing Plant	CAA/RMP	Inspection	Springdale	AR	5/9/2017	High Risk, NEI
Grayson Field Gas Plant	CAA/RMP	Inspection	Magnolia	AR	5/16/2017	High Risk
Rowlett Creek Regional WWTP	CAA/RMP	Inspection	Plano	TX	5/17/2017	High Risk, Incident
Leprino Food Company	CAA/RMP	Inspection	Roswell	NM	5/23/2017	High Risk, NEI
NTMWD Wylie Water Treatment Plt.	CAA/RMP	Inspection	Wylie	TX	5/31/2017	High Risk, NEI
Tarrant County Water Supply Project	CAA/RMP	Inspection	Eules	TX	6/6/2017	High Risk
Ruiz Food Products Inc.	CAA/RMP	Inspection	Denison	TX	6/28/2017	High Risk, NEI
Tom Thumb Alliance Distribution	CAA/RMP	Inspection	Roanoke	TX	7/11/2017	High Risk, NEI
Jasper Water Treatment Plant	CAA/RMP	Inspection	Wichita Falls	TX	7/18/2017	High Risk

NALCO Champion	CAA/RMP	Inspection	Corsicana	TX	8/8/2017	High Risk, NEI
Golden Road WTP	CAA/RMP	Inspection	Tyler,	TX	8/15/2017	
Bowie Water Treatment Plant	CAA/RMP	Inspection	Bowie	TX	8/22/2017	
Cobbs Compressor Station	CAA/RMP	Inspection	Ramona	OK	8/23/2017	High Risk